

SPECIFICATIONS:

Service: Air and combustible, compatible gasses.

Accuracy: +/- 1.5% F.S. from 32 to 104° F / 0 to 40° C

Pressure limits: -20" w.c. to 20" w.c.

Temperature Limits: 32 to 104 ° F / 0 to 40°C.

Storage Temperature Limits: -4 to 176°F / -20 to 80°C

Resolution: 0.05" from -9.95" w.c. to +9.95" w.c. 0.1" < -10" w.c., > +10" w.c.

Power Requirements: 9 volt alkaline battery (Up to 50 hours of operation).

Weight: 10.8 oz / 306g

Connections: Barbed connection for use with 1/8" (3.18mm) or 3/16" (4.76mm) I.D. tubing.

Agency Approvals: CE.

Size: 6-9/16" H x 2-13/16" W x 29/32" D

OPERATING INSTRUCTIONS

On/Off Operation

Press the On/Off key to switch the unit on and off

Zeroing pressure units

Press the Zero key to zero the display

Overpressure

Exceeding the range of the manometer will not damage it or affect calibration if the maximum pressure is not exceeded. Do not exceed the maximum rated pressure as doing so will cause permanent damage to the sensor and may rupture the housing and/or cause injury. The maximum pressure is shown on the rear label of the manometer and on these instructions.

DWYER INSTRUMENTS INC.
102 HIGHWAY 212, MICHIGAN CITY, IN. 46360

PHONE: 219-879-8000

FAX: 219-872-9057

Email: info@dwyer-inst.com

<http://www.dwyer-inst.com>

CE

Copyright 2003 Dwyer Instruments